

Tabella di conversione unità di misura d'inclinazione

Angle Conversion Chart						
	degrees	arc minutes	arc seconds	μradians	mm/m	inches/ft
degrees =	1	60	3600	17453	17.45	0.2094
arc minutes =	0.01667	1	60	290.9	0.2909	3.46x10 ⁻³
arc seconds =	2.78x10 ⁻⁴	0.01667	1	4.848	4.85x10 ⁻³	5.82x10 ⁻⁵
μradians =	5.73x10 ⁻⁵	3.44x10 ⁻³	0.2063	1	0.001	1.20x10 ⁻⁵
mm/m =	0.0573	3.436	206.3	1000	1	0.0120
inches/ft =	4.775	286.5	17,189	83,333	83.33	1